

Western Enterprises

875 Bassett Road

Westlake, OH 44145-1142 **Toll Free:** 800.783.7890

Phone: 440.871.2160

Email: <u>sales@westernenterprises.com</u> **Website:** www.westernenterprises.com

ITEM # CV-7R, OXYGEN GAS RIGHT HAND B-SIZE MALE TO B-SIZE FEMALE NUT TORCH STYLE CHECK VALVE

Torch Model, B-Size (9/16"-18)

Mounts easily on torch, is readily seen and can be removed for periodic testing. Flows cut up to 12" steel plate or handle heating tips (1200 SCFH at 50 PSIG). Stops reverse flow at point of origin.

Oxygen RH, B-Size Male to B-Size Female Nut, to 125 PSIG (800kPa).



Specifications | Check Valve Flow Specifications Charts | Additional Information | Prop 65 | Note

Specifications	
Field	Industrial
Model	Torch
Thread Size	9/16 in
Number of Threads per Inch	18
Maximum Working Pressure	125 psig
Gas Service	CGA-022
Gas	Oxygen
Valve Seat Material	Buna-N™

Check Valve Flow Specifications Charts	
	Flow curves presented here are
	based on air at 70 °F. To convert
Check Valve Flow Specifications Charts	flows of other gases, multiply by
	the appropriate conversion factor

listed on instruction sheets included with all check valves.

Additional Information	Western's reverse flow Check Valves meet or exceed CGA and OSHA requirements (Pamphlet CGA-E2) and feature: • Flows for cutting up to 12" of steel • Machined high quality brass with stainless steel operating spring and valve disc • Low open/close pressures: 1 - 1-1/2 PSIG open valve and 10 oz. reverse pressure to positively close valve • 100% tested • Made in U.S.A.	
------------------------	---	--

Prop 65	
Warning	This product can expose you to lead, which is known to the State of California to cause cancer and birth defects or other reproductive harm.

	Note	
	Note	Check Valves Do Not Stop Flashbacks.
		UL Listed