


J121 Size Chart

Measurement		M	L	XL	2XL	3XL	4XL	5XL	
A	Chest	cm	120	130	140	150	155	160	165
		in	47-1/4"	51-1/6"	55-1/8"	59"	61"	63"	65"
B	Center back length	cm	68.5	70	71	72.5	73.5	75	76
		in	27"	27-5/9"	28"	28-1/2"	29"	29-1/2"	30"
C	Shoulder width	cm	51	53.5	56	58.5	60.5	62	64
		in	20"	21"	22"	23"	23-5/6"	24-2/5"	25-1/5"
D	Armhole straight	cm	28.5	29.5	30.5	31.5	32.5	33.5	34.5
		in	11-2/9"	11-3/5"	12"	12-2/5"	12-4/5"	13-1/5"	13-4/7"
E	Sleeve length	cm	65	66	67.5	68.5	70	71	72.5
		in	25-3/5"	26"	26-4/7"	27"	27-5/9"	28"	28-1/2"
F	Sleeve opening	cm	30	30	31	31	32	32	33
		in	11-4/5"	11-4/5"	12-1/5"	12-1/5"	12-3/5"	12-3/5"	13"
G	Collar width	cm	20.5	21	21.5	22	22.5	23	23.5
		in	8"	8-1/4"	8-1/2"	8-2/3"	8-6/7"	9"	9-1/4"
H	Collar height	cm	8	8	8	8	8	8	8
		in	3-1/7"	3 1/7"	3-1/7"	3-1/7"	3-1/7"	3-1/7"	3-1/7"
I	Front drop neck	cm	9.5	10	10.5	11	11.5	12	12.5
		in	3-3/4"	4"	4-1/7"	4-1/3"	4-1/2"	4-5/7"	5"



NECK DROPS



CORDOVA
SAFETY PRODUCTS